

Download 2003 Gmc Idle Speed Adjustment

GMC Yukon XL Denali Stalling or Low Engine Idle Speed Due to Dirty Throttle Body - 60 reports. Learn about this problem, why it occurs, and how to fix it. View and Download GMC 2003 Sonoma owner's manual online. 2003 Sonoma Automobile pdf manual download. View and Download GMC Envoy XL 2003 owner's manual online. Envoy XL 2003 Automobile pdf manual download. rough idle, stalling, loss of power. - o2 sensor code 44 (lean) Replaced: coolant temp sensor, tps, map sensor, fuel filter, and o2 sensor. It will run ...